

**Cordova: Airport Runway Safety Area****FY2008 Request: \$3,200,000**  
**Reference No: 40271****AP/AL:** Allocation  
**Category:** Transportation  
**Location:** Cordova**Project Type:** Construction**House District:** Cordova/Southeast Islands**Contact:** John Torgerson**Contact Phone:** (907)269-0724**Estimated Project Dates:** 07/01/2007 - 06/30/2012**Appropriation:** Airport Improvement Program**Brief Summary and Statement of Need:**

Re-grade the runway safety areas and improve and replace failing drainage structures. Other improvements will include replacement of lighting and clearing and grubbing. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

<b>Funding:</b>	<b>FY2008</b>	<b>FY2009</b>	<b>FY2010</b>	<b>FY2011</b>	<b>FY2012</b>	<b>FY2013</b>	<b>Total</b>
Fed Rcpts	\$3,200,000						\$3,200,000
Total:	\$3,200,000	\$0	\$0	\$0	\$0	\$0	\$3,200,000

<input checked="" type="checkbox"/> State Match Required	<input type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input checked="" type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
5% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
Totals:	0	0

**Additional Information / Prior Funding History:**

FY2006 - \$8,000,000.

**Project Description/Justification:**

Runway 9/27 does not meet grading requirements for sight distance. The Runway 27 safety area will be raised to improve sight distance. Additionally, old inlet boxes and culverts originally placed in the safety area when the airport was constructed approximately 50 plus years ago are failing. Surface water is flowing around the outlets washing away the embankment. The resulting depressions on the surface are large craters that do not meet safety area standards. The lighting system is failing. This project is intended to compete for discretionary funding.